

>>> Service Letter

Technical Aspects are FAA Approved

Number: L01-03 B
Replaces L01-03 A

Date: 07/19/2005

Subject: Installation, operation and maintenance for Superior Oil Sump.

Application:

Oil Sump Assemblies	ENGINE APPLICATIONS
SL78915	O-360-A1A, -A1AD, -A1D, -A1F6, -A1F6D, - A1LD, -A1P, -A2A, -A2D, -A2E, -A2F, -A3A, -A3AD, -A4A, -A4M, -A4N, -A4P, -A5AD, -B2A, -B2C, -C1A, - C1C, -C1E, -C1G, -C2A, -C2C, -C2E, -C4P, -D2A, -D2B, -J2A
SL13861	IO-360-B1A, -B1B, -B1D, -B1F, -B2F, -B2F6, -B4A, - L2A AEIO-360-B1G6, -H1A

Compliance:

These Superior Air Parts PMA Oil Sump Assemblies are approved replacement for those Lycoming parts that have the same engine model eligibility's as those listed above.

These Superior Air Parts Oil Sump Assemblies are to be installed, operated and maintained in accordance with the applicable original equipment manufacturer's overhaul and operator's manuals or other applicable service documents. Repair and overhaul information is given in Superior Service Letter No. L01-04.

Failure to comply with these instructions may result in damage to the Oil Sump assemblies and/or engine or render them unsafe.