

Service Letter

Technical Aspects are FAA Approved

Number: L01-21 A

Replaces ServL 101-021

Date: 07/12/2004

Subject: Installation, operation and maintenance for Superior Starter Ring Gear Support

Application:

SUPORT ASSEMBLY	ENGINE APPLICATIONS
SL77579	AEIO-360-A1E, -B1G6, -H1A AEIO-540-D4A5,-D4B5,-L1B5, -L1B5D AIO-360-A1A, -A1B, B1B HIO-360-A1A, -B1A, -C1A, -C1B, -D1A, -E1AD, -E1BD, -F1AD HO-360-C1A IO-360-A1A, -A1B, -A1B6, -A1B6D, -A1C, -A1D, -A1D6, -A2A, -A2B, -A3B6D, -B1B, -B1D, -B1E, -B1F, -B2F, -B2F6, -B4A, -C1B, -C1C, -C1D6, -C1E6, -C1F, -J1A6D, -M1A IO-540-A1A5, -B1C5, -C4B5, -C4C5, C4D5D,-D4A5, -E1B5, -G1A5, -G1C5, -G1D5, -G1E5, -J4A5, -K1A5, -K1B5, -K1D5, -K1K5,-N1A5, -R1A5,-V4A5D, -V1F5D, -K1F5D, -K1G5D, -K1J5D, -T4A5D, -T4B5D, -L1C5 O-360-A1A, -A1AD, -A1D, -A1F6, -A1F6D, -A1G6, -A1G6D, -A1LD, A2A, -A2D, -A2F, -A2G, -A3A, -A3AD, -A4A, -A4G, -A4J, -A4K, -A4N, -A5AD, -B2C, -C1G, -C1A, -C1E, -C1F, -C2A, -C2E, -C4F, -C4P, -D2A, -F1A6 O-540-A1C5, -A1D5, -B1A5, -B2B5, -B2C5, -B4B5, -E4A5, -E4B5, -E4C5, -G1A5, -G2A5,- H1B5D,-H2B5D TIO-360-A1B, -C1A6 TIO-540-AA1AD, -AB1AD, -A2C, -C1A, -F2BD, -J2B, -J2BD, -N2BD, -R2AD, -S1AD, V2AD LTIO-540-V2AD TO-360-C1A6D

Application (cont.):

SUPPORT ASSEMBLY	ENGINE APPLICATIONS
SL68867	IO-320-E2A O-320-A2A, -A2B, -A2C, -A3A, -A3B, -A3C, -B2A, -B2B, -B3A, -B3B, -D2A, -D2B, -E2A, -E2B, -E2D, -E2H

Compliance:

These Superior Air Parts PMA Support Assemblies are approved replacements for those Lycoming parts that have the same engine model eligibility's as those listed above.

These Support Assemblies are to be installed, operated and maintained in accordance with the applicable original equipment manufacturer's overhaul and operator's manuals or other applicable service documents. Repair and overhaul information is given in Superior Service Letter No. L01-22.

Failure to comply with these instructions may result in damage to the Support Assembly and/or engine or render them unsafe.