

>>> Service Letter

Technical Aspects are FAA Approved

Number: L94-02 A

Replaces ServL94-002


Date: 07/13/2004

Subject: Textron Lycoming Service Bulletin No. 519, dated May 25, 1994.

Superior has supplied, both individually and in gasket sets, the affected LW14995 shroud tube retaining springs, beginning May 5, 1994, continuously to the date of this Service Letter. The following gasket sets with date codes of 5194, 5294, 5394, and 5494 (last line on the label) are affected by this Service Letter 94-002:

Figure 1

SL12945	SL69371-1
SL13377	SL71569-1
SL14815	SL75439-1



Date Code

The following actions should be taken for any of the above items that were ordered from Superior Air parts, Inc. on May 5, 1994, through June 1, 1994.

Any gasket sets listed in Figure 1, above, dated 5194, 5294, 5394, 5494, or individual LW14995 shroud tube retaining springs ordered on May 5, 1994, through June 1, 1994, but not installed, should be returned to Superior Air Parts, Inc. for a refund of the gasket set cost or shroud tube retaining springs cost, plus surface freight expense.

Shroud tube retaining springs purchased individually or in gasket sets, May 5, 1994, through June 1, 1994, from Superior Air parts, Inc. and installed, must comply with Textron Lycoming Service Bulletin No. 519 (see attached). The removed shroud tube retaining springs should be returned to Superior Air Parts, Inc. no later than April 25, 1995, in order to be eligible for credit. Please enclose a completed TLRED Warranty Application and Material form with your parts (see attached).

All affected parts, individually or in gasket sets, should be returned via surface freight prepaid to:

Superior Air Parts, Inc.
621 S. Royal Lane,
Suite 100
Dallas, TX 75019

Identify all returns as "LW14995 Returns" on the mailing label.