

>>> Service Letter

Technical Aspects are FAA Approved

Number: L98-01 A

Replaces ServL 98-001

Date: 07/14/2004

Subject: Teledyne Continental Critical Service Bulletin CSB98-1B

Application:

Cylinder / Stud Assemblies	Engine Application	Serial Numbers
SA10200-A20P	O-200-A,B; C-125-2; C145-2,2H; O-300-A,B,C,D	C98-17344 to C98-17472 C98-17344 to C98-17472 D98-17522 to D98-17533
SA10200-A21P	C-75; C-85	C98-17343 D98-17510 to D98-17513
SA10200-A22P	C-90	C98-17481 to C98-17485 D98-17514 to D98-17521

Compliance: Inspection as required by Continental Service Bulletin CSB98-1B

Scope:

Superior Air Parts, Inc. has recently become aware of an issue with Teledyne Continental intake and exhaust valves manufactured by TRW. It is reported that these valves exhibit abnormal tip wear due to improper heat treatment.

Due to inventory shortages Superior was forced to purchase a quantity of affected TCM 641792 intake valves. The intake valves were installed in Superior Air Parts, Inc. Millennium® Cylinders from 3/25/98 to 4/8/98. Reference the above part and serial numbers.

Any person(s) in possession of or operating the above referenced Millennium® Cylinders is recommended to comply with Teledyne Continental Critical Service Bulletin CSB98-1B. Any inspections, testing, part replacement or reimbursement required by TCM CSB98-1B, **Must be coordinated through Teledyne Continental Motors.**

For further information please contact your nearest Superior Air Parts, Inc. Customer Service and Technical Center at 1-800-487-4727 or TCM.