

>>> Service Letter

Technical Aspects are FAA Approved

Number: L99-04 A

Replaces ServL 99-004

Date: 07/14/2004

Subject: Installation, operation and maintenance for SA52000 cylinder.

Application:

CYLINDER ASSEMBLY	APPLICATIONS – Teledyne Continental Engines
SA52000-A20P (Piston P/N SA648013)	IO-520-A, B, BA, C, D, E, F, J, K, L, M, BB, CB, MB
SA52000-A21P (Piston P/N SA631475)	IO-520-A, B, BA, C, D, E, F, J, K, L, M, BB, CB, MB
SA52000-A22P (Piston P/N SA648044)	TSIO-520-B, BB, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, VB, WB
SA52000-A23P (Piston P/N 654857)	IO-550-A, B, C

Compliance:

These Millennium® cylinder power assemblies are approved replacements for those TCM parts that have the same engine model eligibilities as those listed above. Millennium® cylinders may be used individually or in sets.

CAUTION: Do not mix piston part numbers in the same engine.

These Millennium® aircraft cylinder assemblies are to be installed, operated and maintained in accordance with the applicable original equipment manufacturer's overhaul and operator's manuals or other applicable service documents. Failure to comply with these instructions may result in damage to the cylinders and/or engine or render them unsafe.