

>>> Service Letter

Technical Aspects are FAA Approved

Number: L01-01 A
Replaces ServL01-001

Date: 07/15/2005

Subject: Installation, operation and maintenance for Superior Accessory Housing

Application:

Accessory Housing Assembly	ENGINE APPLICATIONS
SL10482	O-360-A3A IO-360-C1C, -C1C6, -C1E6, -A1B, -A1B6, -A1D, -A1D6, -A2B, -B4A AIO-360-A1B, -B1B
SL76110	AEIO-360-A1E, -H1A AIO-360-A1B, -B1B AIO-320-B1B, -C1B IO-320-D1A, -D1B IO-360-A1B, -A1B6, -A1D, -A1D6, -A2B, -A4A, -C1C, -C1D6 O-320-A2A, -D1A, -D1F, -D2A, -D2C, -D2G, -E1A, -E1F, -E2A, -E2B, -E2C, -E2F O-360-A1A, -A1F6, -A2A, -A2F, -A3A, -A4A, -A4M, -B2A, -B2C, -C1A, -C1E, -C1G, -C2A, -C2E, -C4P, -D2A

Accessory Housing Assembly	ENGINE APPLICATIONS
SL76111	O-320-D2B, -E2B O-360-A1D, -A2D, -C2C, -D2B IO-360-A1A, -B1B, -C1B, -A1C, -A2A AIO-360-A1A
SL77997	AEIO-360-B1G6, -H1A O-360-A1A, -A2A, -A4N, -C1E, -C2A, -C2E, -F1A6 IO-360-B1F, -B2F, -B2F6 AIO-360-A1B

These Superior Air Parts PMA Accessory Housing Assemblies are approved replacements for those Lycoming parts that have the same engine model eligibility's as those listed above.

These Accessory Housing Assemblies are to be installed, operated and maintained in accordance with the applicable original equipment manufacturer's overhaul and operator's manuals or other applicable service documents. Repair and overhaul information is given in Superior Service Letter No. L01-02.

Failure to comply with these instructions may result in damage to the Accessory Housing Assembly and/or engine or render them unsafe.