

»» **Service Letter**

Technical Aspects are FAA Approved

Number: L91-02A

Replaces ServL91-002

Date: 07/13/2004

Subject: Compliance with Airworthiness Directives, Letters, Bulletins and Instructions.

Application: Wherever Superior FAA-PMA replacement parts are used.

Superior has received inquiries about Federal Aviation Administrative (FAA) Airworthiness Directives and Original Equipment Manufacturers (OEM) service information which, apply to OEM part numbers that are similar to Superior PMA part numbers. This service letter is being issued to clarify this issue.

Only FAA Airworthiness Directives that specifically name Superior Air Parts, Inc. and include Superior prefix "SA" or "SL Part numbers" (Example: SA646303 is a Superior part) apply to Superior Parts.

The overhaul inspection criteria, tolerances, fit and installation instructions as published by the Original Equipment Manufacturer (OEM) apply to Superior parts except where Superior has published alternative data in the form of FAA Approved Service Letters or Service Bulletins.

OEM Service Letters, Bulletins and Instructions do not necessarily apply to Superior parts. Any necessary service actions other than overhaul inspection criteria, tolerances, fit and installation instructions as published by the OEM will be provided by Superior Service Letters or Service Bulletins. Questions regarding applicability of OEM Service Letters, Instructions, Bulletins, etc should be directed to the Superior Technical Support Center at (800) 420-4727.