

**>>> Service Letter**

Technical Aspects are FAA Approved

**Number: L98-02 B**

**Replaces ServL 98-002A**

**Date:** 07/14/2004

**Subject:** Installation, operation and maintenance of SL36000NL and SL36000WL cylinders.

**Application:**

CYLINDER ASSEMBLY	APPLICATIONS - Textron Lycoming Engines
SL36000NL-A20P (Piston P/N SL75089A)  SL36000NL-A21P (Piston P/N SL75413A)  SL36000WL-A20P (Piston P/N LW-12733)	IO-540-J4A5, R1A5  TIO-540-G1A  TIO-540-C1A, E1A  TIO-540- AB1AD, K1AD
SL36000WL-A21P (Piston P/N SL75413A)	TIO-540-C1A, C1AD

**Compliance:**

These Millennium® cylinder power assemblies are approved replacements for those Lycoming parts that have the same engine model eligibilities as those listed above. Millennium® cylinders may be used individually or in sets.

These Millennium® aircraft cylinder assemblies are to be installed, operated and maintained in accordance with the applicable original equipment manufacturer's overhaul and operator's manuals or other applicable service documents. Failure to comply with these instructions may result in damage to the cylinders and/or engine or render them unsafe.