

>>> Service Letter

Technical Aspects are FAA Approved

Number: L99-02 A

Replaces ServL 99-002

Date: 07/14/2004

Subject: Installation, operation and maintenance For SA55000 Cylinder procedures for Cylinder Power Assemblies using P/N SA55000-A1 Cylinder Stud Assembly

Application:

CYLINDER ASSEMBLY	APPLICATIONS – Teledyne Continental Engines
SA55000-A20P (Piston P/N 654857) (Tapered Cooling Fins On Barrel)	IO-550-D, E, F and L

Compliance:

These Millennium® aircraft cylinder assemblies are to be installed, operated and maintained in accordance with the applicable original equipment manufacturer's overhaul and operator's manuals or other applicable service documents. Failure to comply with these instructions may result in damage to the cylinders and/or engine or render them unsafe.