

>>> Service Letter

Technical Aspects are FAA Approved

Number: L00-07 A

Replaces L100-007

Date: July 2, 2004

Subject: Installation, operation and maintenance for SL360006W Cylinder

Application:

CYLINDER ASSEMBLY	ENGINE APPLICATIONS
SL36006W-A20P (Piston P/N SL75089A)	AEIO-360-B1B, B1D, B1F, B1F6, B1G6, B2F, B2F6, B4A, H1A
	HIO-360-B1A, B1B
	IO-360-B1B, B1BD, B1D, B1E, B1F, B1F6, B2E, B2F, B2F6, B4A, E1A, F1A
	LO-360-A1G6D, A1H6
	O-360-A1A, A1AD, A1D, A1F, A1F6, A1F6D, A1G, A1G6, A1G6D, A1H, A1H6,A1J, A1LD, A2A, A2D, A2F, A2G, A2H, A3A, A3AD, A3D, A4A, A4AD, A4D, A4G, A4J, A4JD, A4K, A4M, A4N, A5AD, C1A, C1C, C1E, C1F, C1G, C2A, C2B, C2C, C2D, C2E, F1A6, G1A6
	AEIO-540-D4B5, D4C5
	IO-540-C4A5, C4B5, C4B5D, C4D5D, D4A5, D4B5, D4C5, N1A5, N1A5D, T4A5, T4A5D, T4B5D, T4C5D, V4A5D
	O-540-A4D5, E4A5, E4B5, E4B5D, E4C5, GIA5, G1A5D, H1A5D, H1B5, H1B5D, H2A5, H2A5D, H2B5D



Service Letter

Number: L00-07

CYLINDER ASSEMBLY	ENGINE APPLICATIONS
SL36006W-A21P (Piston P/N SL75413A)	O-360-B1A, D2A
,	O-540-B2C5, B2C5D, B4B5, B4B5D

Compliance:

These Millennium Standard Cast® cylinder power assemblies are approved replacements for those Lycoming parts that have the same engine model eligibilities as those listed above. Millennium Standard Cast® cylinders may be used individually or in sets.

These Millennium Standard Cast® aircraft cylinder assemblies are to be installed, operated and maintained in accordance with the applicable original equipment manufacturer's overhaul and operator's manuals or other applicable service documents. Failure to comply with these instructions may result in damage to the cylinders and/or engine or render them unsafe.