

>>> Service Letter

Technical Aspects are FAA Approved

Number: L01-11 B

Replaces ServL 101-011 A

Date: 05/11/2005

Subject: Installation, operation and maintenance procedures for Superior Propeller Governor

Adapter Assemblies

Application:

PROPELLER GOVERNOR ADAPTER	ENGINE APPLICATIONS
SL75545	IO-360-A1A, -A1B, -A1B6, A1C, A1D, -B1B, -B1E, -C1A, -C1B, -C1C, -C1C6, -C1D6, -C1F
	O-360 –A1A, -A1D, -A1F6, -A1G6
	AEIO-360-B1G6, -H1A
	IO-320-B1A, -B1C, -C1A, -E1A, -E1B
	LIO-320-B1A, -C1A
	O-320-A2A, -A3B, -A3A, -A3A, -A3C, -B3B, -B3C, -D1A, -D1D, E1A, -E2C
SL78594	IO-360-A1A, -A1B, -A1B6
	O-360 -A1A,-A1D, -A1F6

Compliance:

These Superior Air Parts PMA Propeller Governor Adapter Assemblies are approved replacement for those Lycoming parts that have the same engine model eligibility's as those listed above.

These Superior Air Parts Propeller Governor Adapter Assemblies are to be installed, operated and maintained in accordance with the applicable original equipment manufacturer's overhaul and operator's manuals or other applicable service documents. Repair and overhaul information is given in Superior Service Letter No. L01-12.

Failure to comply with these instructions may result in damage to the gear assemblies and/or engine or render them unsafe.