

>>> Service Letter

Technical Aspects are FAA Approved

Number: L03-03 B

Replaces Servi L03-03 A

Date: 07/02/2004

Subject: New Engine Gasket Material

Application:

Compliance

Superior Parts Inc. has replaced the material used on many of its FAA-PMA gaskets. The new gasket material MP-15, manufactured by Interface Solutions, contains a high quality man-made fiber. The new gasket material may be identified by its reddish brown color.

Superior tested and approved MP-15 material on a 300 plus hour, FAA monitored, engine test. There was no leakage, shrinkage, swelling or gasket movement detected and test results were excellent.

Superior does not recommend the use of gasket compound or solvent type materials with the MP-15 gasket material. MP-15 exhibits exceptional self-sealing and adhesion on clean petroleum free surfaces. The use of gasket compounds or solvent type materials may result in undesirable gasket performance.