

>>> Service Letter

Technical Aspects are FAA Approved

Number: L11-02 A
INITIAL RELEASE

Date: 4/28/2011

Subject: AVstar Fuel Systems Mandatory Service Bulletin AFS-SB6 and Pending AD for RSA-5 Fuel Injection Servos Overhauled by AVstar or Repaired or Overhauled Using AVstar FAA-PMA Replacement Parts

Application:

No engines or RSA-5 fuel injector servos supplied by Superior contained fuel servos or parts manufactured by AVstar Fuel Systems. However, in the interest of safety, this Service Letter is issued as a courtesy to our customers that may have had RSA-5 fuel injector servos overhauled by AVstar Fuel Systems or repaired or overhauled using AVstar FAA-PMA replacement parts. Superior has been notified by the FAA of the existence of AVstar Mandatory Service Bulletin AFS-SB6, Rev. 2 and of a pending Airworthiness Directive that will be issued shortly.

Compliance:

Please refer to the AVstar Fuel Systems web site for a copy of Service Bulletin AFS-SB6, Rev. 2.