

## >>> Service Letter

**Technical Aspects are FAA Approved** 

Number: L98-05 D

Replaces L98-05 C

Date: 04/28/2005

**Subject:** Installation, operation and maintenance of SL36000TW, SL36000TWL Cylinder.

## Application:

CYLINDER ASSEMBLY	APPLICATIONS - Textron Lycoming Engines
SL36000TW-A20P (Piston P/N LW-13396)	O-540-J1A5D, J2A5D, J3A5D and J3C5D
(FISION F/N EW-13390)	IO-540-AB1A5, W1A5D and W3A5D
SL36000TW-A21P	O-360-J2A
(Piston P/N SL75089A)	O-540-F1B5
SL36000TW-A22P	O-540-J3A5
(Piston P/N LW-13396)	
SL36000TWL-A20P (Piston P/N SL75089A)	O-540-L3C5D

These Millennium® cylinder power assemblies are approved replacements for those Lycoming parts that have the same engine model eligibilities as those listed above. Millennium® cylinders may be used individually or in sets.

These Millennium® aircraft cylinder assemblies are to be installed, operated and maintained in accordance with the applicable original equipment manufacturer's overhaul and operator's manuals or other applicable service documents. Failure to comply with these instructions may result in damage to the cylinders and/or engine or render them unsafe.