

>>> Service Letter

Technical Aspects are FAA Approved

Number: L99-10 A
Replaces ServL 99-10

Date: 07/14/2004

Subject: Installation, operation and maintenance for SA47000L cylinder.

Application:

CYLINDER ASSEMBLY	APPLICATIONS – Teledyne Continental Engines
SA47000L-A20P (Piston P/N SA648029)	O-470-U IO-470-D, E, F, L, M, N, S, U, V

Compliance:

These Millennium® cylinder power assemblies are approved replacements for those TCM parts that have the same engine model eligibilities as those listed above. Millennium® cylinders may be used individually or in sets.

These Millennium® aircraft cylinder assemblies are to be installed, operated and maintained in accordance with the applicable original equipment manufacturer's overhaul and operator's manuals or other applicable service documents. Failure to comply with these instructions may result in damage to the cylinders and/or engine or render them unsafe.