

PRODUCTION APPROVAL LISTING - SUPPLEMENT 102, REV. 1

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

Superior Air Parts, Inc.

NOMENCLATURE AND PART NUMBER	APPROVED REPLACEMENT FOR	FAA DESIGN DATA AND APPROVAL MEANS	APPROVED FOR INSTALLATION ON
SAX-1473 Washer, copper	Teledyne Continental Part No. X-1473	FAA approved Superior Air Parts, Inc. Dwg. No. SAX-1473 Rev. n/c dtd. 07/23/85 or later FAA approved revision.	Continental Eng. IO-360-A, C, D, G, H, J, K TSIO-360-A, B, C, D, H, JB, MB O-470-A, B, E, G, J, K, L, M, P, R, S, U IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U TSIO-470-B, C, D IO-520-A, BA, C, D, E, F, J, K, L, M, BB, CB, MB TSIO-520-B, D, E, J, K, L, N, UB, VB, WB, BE, C, G, H, M, P, R, T, AF, AE, BB, DB, EB, JB, KB, LB, NB GTSIO-520-C, D, F, H, K, L, M, N IO-550-B, C
SA21218 Bolt	Teledyne Continental Part No. 21218	FAA approved Superior Air Parts, Inc. Dwg. No. SA21218 Rev. B dtd. 10/07/86 or later FAA approved revision.	Continental Eng. C-75, 85, 90 O-200-A, B
SA21247 Nut	Teledyne Continental Part No. 21247	FAA approved Superior Air Parts, Inc. Dwg. No. SA21247 Rev. n/c dtd. 06/26/74 or later FAA approved revision.	Continental Eng. TSIO-470-B1, B2, B3, C, D

PRODUCTION APPROVAL LISTING - SUPPLEMENT 102, REV. 1

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

Superior Air Parts, Inc.

<u>NOMENCLATURE AND PART NUMBER</u>	<u>APPROVED REPLACEMENT FOR</u>	<u>FAA DESIGN DATA AND APPROVAL MEANS</u>	<u>APPROVED FOR INSTALLATION ON</u>
SA22800 Hose, int.	Teledyne Continental Part No. 22800	FAA approved Superior Air Parts, Inc. Dwg. No. SA22800 Rev. n/c dtd. 11/22/71 or later FAA approved revision.	Continental Eng. A65 A75 C75 C85 C90 O-200-A, B C-125 C-145-2, 2H O-300-A, B, C, D
SA24239 Washer	Replacement for Teledyne Continental Part No. 24239	FAA approved Superior Air Parts, Inc. Dwg. No. SA24239 Rev. n/c dtd. 11/26/84 or later FAA approved revision.	Continental Eng. O-470-A, B, E, G, J, K, L, M, P, R, S, U IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V TSIO-470-B, C, D IO-520-A, BA, C, D, E, F, J, K, L, M TSIO-520-C, G, H, M, P, R, T, AF, BE, B, BB, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, VB, WB IO-550-B, C
SA24252 Screw	Teledyne Continental Part No. 24252	FAA approved Superior Air Parts, Inc. Dwg. No. SA24252 Rev. n/c dtd. 11/21/84 or later FAA approved revision.	Continental Eng. A65 A75 C75 C85 C90 O-200-A, B

PRODUCTION APPROVAL LISTING - SUPPLEMENT 102, REV. 1

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

Superior Air Parts, Inc.

NOMENCLATURE AND PART NUMBER	APPROVED REPLACEMENT FOR	FAA DESIGN DATA AND APPROVAL MEANS	APPROVED FOR INSTALLATION ON
SA401893 Stud	Teledyne Continental Part No. 401893	FAA approved Superior Air Parts, Inc. Dwg. No. SA401893 Rev. n/c dtd. 01/21/85 or later FAA approved revision.	Continental Eng. O-470-G, K, L, M, P, R, S, U IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V TSIO-470-B, C, D IO-520-A, BA, C, D, E, F, J, K, L, M TSIO-520-B, D, E, DB, EB, BE GTSIO-520-C, D, F, H, K, L, M TSIO-520-C, G, H, M, R, T
SA532200 Seal	Teledyne Continental Part No. 532200	FAA approved Superior Air Parts, Inc. Dwg. No. SA532200 Rev. n/c dtd. 03/04/68 or later FAA approved revision.	Continental Eng. E-165 Series E-185 Series E-225 Series O-470 Series IO-470 Series TSIO-470 Series
SA535668 Bolt	Teledyne Continental Part No. 535668	FAA approved Superior Air Parts, Inc. Dwg. No. SA535668 Rev. n/c dtd. 07/05/85 or later FAA approved revision.	Continental Eng. O-470-M IO-470-D, L, U, V TSIO-470-B, C, D IO-520-A Specs. 9, 12, 7, 22, 24, 30, 34; F Specs. 2, 9, 11, 13, 17; L specs. 3, 7 TSIO-520-C, G, H, M, P, R
SA535823 Gasket, ass'y	Teledyne Continental Part No. 535823	FAA approved Superior Air Parts, Inc. Dwg. No. SA535823 Rev. B dtd. 08/21/85 or later FAA approved revision.	Continental Eng. O-470-A, B, E, G, J, K, L, M, P, R, S, U IO-470-C, D, E, F,

PRODUCTION APPROVAL LISTING - SUPPLEMENT 102, REV. 1

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

Superior Air Parts, Inc.

<u>NOMENCLATURE AND PART NUMBER</u>	<u>APPROVED REPLACEMENT FOR</u>	<u>FAA DESIGN DATA AND APPROVAL MEANS</u>	<u>APPROVED FOR INSTALLATION ON</u>
SA535823 Gasket, cap ass'y (cont'd)	Teledyne Continental Part No. 535823	FAA approved Superior Air Parts, Inc. Dwg. No. SA535823 Rev. B dtd. 08/21/85 or later FAA approved revision.	Continental Eng. IO-470 (cont'd) G, H, J, K, L, M, N, P, R, S, U, V IO-520-A, D, E, F, J, K, L TSIO-520-C, G, H, M, P, R, T, AF, AE, CE GTSIO-520-C, D, F, H, K, L, M, N
SA536410 Screw	Teledyne Continental Part No. 536410	FAA approved Superior Air Parts, Inc. Dwg. No. SA536410 Rev. n/c dtd. 06/19/68 or later FAA approved revision.	Continental Eng. IO-346-A O-470-A, E, J IO-470-J, K
SA626487 Screw	Teledyne Continental Part No. 626487	FAA approved Superior Air Parts, Inc. Dwg. No. SA626487 Rev. n/c dtd. 07/23/85 or later FAA approved revision.	Continental Eng. C-125-2 C-145-2, 2H GO-300-A, C, D, E IO-360-A, C, D, G, H, J, K IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V IO-520-A, D, E, F, J, K, L IO-550-D, E, F, L LTSIO-360-E, KB LTSIO-520-AE O-300-A, B, C, D O-470-A, B, E, G, J, K, L, M, R, S, U TSIO-360-A, B, C, D, E, F, GB, H, JB, KB, LB, MB TSIO-520-AE, AF, C, CE, G, H, M, P, R, T

PRODUCTION APPROVAL LISTING - SUPPLEMENT 102, REV. 1

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

Superior Air Parts, Inc.

NOMENCLATURE AND PART NUMBER	APPROVED REPLACEMENT FOR	FAA DESIGN DATA AND APPROVAL MEANS	APPROVED FOR INSTALLATION ON
SA632085 Gasket, annular	Teledyne Continental Part No. 632085	FAA approved Superior Air Parts, Inc. Dwg. No. SA632085 Rev. n/c dtd. 10/28/85 or later FAA approved revision.	Continental Eng. A65 C75 C85 C90 IO-346 IO-470-C, E, F, G, H, J, K, N, R, S IO-520-A, B, BA, BB, D, F, J, K, L IO-550-D, F, G, L O-470-A, G, P, R, S TSIO-520-AF, C, CE, D, DB, G, H, M, P, R, T, UB

END OF LISTING

W.A. Griggs for
Allen K. Griggs
 Manager, DFW MIDO

9-12-95
 Date

Date amended: 08/26/93
 Date of original issue: 06/17/92

Revision 1 added new engine models to the eligibility listing.

This supplement is an attachment to FAA-PMA letter dated 06/11/79.