

Service Letter

Technical Aspects are FAA Approved

Number: L01-09 A
Replaces ServL01-09

Date: 07/12/2004

Subject: Installation, operation and maintenance for Superior Vacuum Pump Adapter.

Application:

Vacuum Pump Adapter	ENGINE APPLICATIONS
SL61098	O-235-C1, -C2A, -C1B, -C2C, -F2A, -F2B, -J2A, -K2A, -K2B, -L2A, -L2C, -M1, -N2A, -N2C, -P2A O-290-D, -D2, -D2B, -D2C IO-360-A1A, -A1B, -A1B6, -A1C, -A1D6, -A2A, -A2B, -B1A, -B1B, -B1D, -B1E, -B1F, -B1G6, -B2F, -B2F6, -B4A, -C1B, -C1C, -C1C6, -C1D6, -C1E6, -C1F, -L2A, -M1A AIO-360-A1A, -A1B, -B1B O-360-A1A, -A1C, -A1D, -A1F6, -A1G6, -A1H6, -A1P, -A2A, -A2D, -A2E, -A2F, -A3A, -A4A, -A4K, -A4M, -A4N, -A4P, -B2A, -B2C, -C1A, -C1C, -C1F, -C1G, -C2A, -C4F, -C4P, -D2A, -F1A6 LIO-360-C1E6 TIO-360-A1B IO-320-B1A, -B1C, -C1A, -D1A, -D1B, -E2A AIO-320-B1B, -C1B LO-360-A1H6 LIO-320-B1A, -C1A O-320-A2A, -A2B, -A2C, -A3A, -A3B, -A3C, -B2A, -B2B, -B2C, -B3A, -B3B, -B3C, -D1A, -D1D, -D1F, -D2A, -D2B, -D2C, -D2G, -D2J, -D3G, -E1A, -E1F, -E2A, -E2B, -E2C, -E2D, -E2F, -E2G, -E2H, -E3D, -E3H

This Superior Air Parts PMA Vacuum Pump Adapter Assembly is an approved replacement for those Lycoming parts that have the same engine model eligibility's as those listed above.

This Superior Air Parts Vacuum Pump Adapter Assembly is to be installed, operated and maintained in accordance with the applicable original equipment manufacturer's overhaul and operator's manuals or other applicable service documents. Repair and overhaul information is given in Superior Service Letter No. L01-10.

Failure to comply with these instructions may result in damage to the Vacuum Pump Adapter assembly and/or engine or render them unsafe.