

**Service Letter**

Technical Aspects are FAA Approved

**Number: L99-12 A**

**Replaces ServL 99-012**

**Date:** 07/14/2004

**Subject:** Installation, operation and maintenance for SL10302 cylinder.

**Application:**

CYLINDER ASSEMBLY	APPLICATIONS – Textron Lycoming Engines
SL10302-A20P (Piston P/N LW-18725)	O-235-F2A, F2B, J2A
SL10302-A21P (Piston P/N SL18729)	O-235-K2A, K2B, K2C, L2A, L2C, M1

**Compliance:**

These Millennium® cylinder power assemblies are approved replacements for those Lycoming parts that have the same engine model eligibilities as those listed above. Millennium® cylinders may be used individually or in sets.

These Millennium® aircraft cylinder assemblies are to be installed, operated and maintained in accordance with the applicable original equipment manufacturer's overhaul and operator's manuals or other applicable service documents. Failure to comply with these instructions may result in damage to the cylinders and/or engine or render them unsafe.